


Wiring Diagram — WD1-12

For External Rotor Motor Type

Single phase motor with internal thermal contacts



Note: Internal thermal overload protection contacts will reset and fan will re-start when temperature reduces after overload.