


Wiring Diagram — WD1-09

For External Rotor Motor Type

Single phase three speed motor with internal capacitor and internal thermal contact



Note: Internal thermal overload protection contacts will reset and fan will re-start when temperature reduces after overload.